

PassTest

Bessere Qualität , bessere Dienstleistungen!



Q&A

<http://www.passtest.de>

Einjährige kostenlose Aktualisierung

Exam : HP0-J56

**Title : 3PAR Solutions Advanced
Service and Support**

Version : Demo

1.Which rules must be followed with regard to disk type, size, and speed in a V400 drive magazine?

- A. Disks must all be of the same type size, and speed
- B. Disk sizes may be mixed, but rotation speed must be the same.
- C. Disks of the same type are required, although disk speeds can be mixed.
- D. Disks of any type, size, and speed can be mixed.

Answer: D

2.Which steps are performed before adding new hardware components to an existing HP 3PAR system?
(Select two)

- A. Preparing an electrostatic discharge safe (ESD) environment
- B. Ensuring power supplies are available
- C. Upgrading the current environment to the latest In Form OS
- D. Checking the health of the system
- E. Updating the service processor

Answer: A,B

3.Which statement is true regarding HP 3PAR Remote Copy?

- A. Supports 4:1 ratio using asynchronous periodic mode
- B. Initial copy will not replicate zeroes
- C. Requires a separate Windows 2008 server to initiate failover
- D. RCIP supports up to 450-500 MB/s

Answer: A

4.What is the lowest level of HP 3PAR service that provides seven day a week, round-the-clock, four-hour onsite response?

- A. Mission Critical
- B. Support Plus 24
- C. Proactive24
- D. AR Array Base Warranty

Answer: C

5.How are the ports numbered on a V400 or V800 PCI adapter?

- A. From left to right
- B. From bottom to top
- C. From right to left
- D. From top to bottom

Answer: A

6.Identify the valid mode used in Adaptive Optimization policies?

- A. Capacity
- B. Availability
- C. Ownership
- D. Balanced

Answer: D

7.Which customer requirement would prompt an EVA recommendation instead of a 3PAR recommendation?

- A. Federation
- B. High availability
- C. Fibre Channel
- D. Journal-based asynchronous replication

Answer: C

8.Which statement is true when comparing F400 and V400 controller nodes?

- A. Control memory has increased from 6 GB to 16 GB.
- B. PCI slots have increased from 6 to 12 per controller node.
- C. Data memory has increased from 6 GB to 16 GB
- D. Maximum battery life has reduced from 25 to 15 minutes when fully charged.

Answer: A

9.Your customer wants an HP 3PAR V400 with four controllers and four DC4 chassis. What is the minimum number of maps per chassis?

- A. Three mags per DC4
- B. Four mags per DC4
- C. Two mags per DC4
- D. One mag per DC4

Answer: B

10.HOTSPOT

Match the correct value with the 3PAR specification.

Maximum number of read/write copies per base volume

Number of controllers in a T800 minimum configuration

Number of built-in IP Remote Copy ports in V800 maximum configuration

Chunklet size (MB) in V400 Storage System

Maximum number of read/write copies per base volume

2
1024
8
256

Number of controllers in a T800 minimum configuration

2
1024
8
256

Number of built-in IP Remote Copy ports in V800 maximum configuration

2
1024
8
256

Chunklet size (MB) in V400 Storage System

2
1024
8
256

Answer:

Maximum number of read/write copies per base volume

2

1024

8

256

Number of controllers in a T800 minimum configuration

2

1024

8

256

Number of built-in IP Remote Copy ports in V800 maximum configuration

2

1024

8

256

Chunklet size (MB) in V400 Storage System

2

1024

8

256